

Fire Related Product Recall Notice

Date issued: 18 December 2014

Lenovo AC Power Cords



Lenovo are recalling certain AC power cords distributed worldwide with Lenovo IdeaPad computers. These computers were sold from February 2011 through June 2012.



LS-15 moulded
marking



Problem

The electrical insulation in the connector may fail causing the connector to overheat. Overheating may cause burn hazards or result in fire.

Details

This recall applies to Power Cords bearing the mark **LS-15 only**. Lenovo sold the power cords with new notebook computers or as replacement parts. This recall applies to **only the AC power cord**. The Adapter that connects to the computer is not being recalled.

What to do

Customers should immediately stop using your power cord immediately. Visit the Lenovo website to see if your power cord(s) is affected. Lenovo customers affected by this program are eligible to receive a replacement AC power cord for the recalled power cord in their possession. If affected you will be asked to register to receive a replacement AC Power Cord.

Contact

For more information and to see if your model is affected contact Lenovo New Zealand Ltd online at <http://www.lenovo.com/nz/en/or> on 0800 446 833

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever