

FIRE RELATED PRODUCT RECALL NOTIFICATION

Westinghouse Dishwashers	
09 Apr 2008 <i>(first recalled 03 December 2007)</i> ACTION - New Zealand recall	
Problem	A wire connector may overheat, causing plastic to melt or in extreme cases, a small fire in the control panel.
Details	<p>Westinghouse dishwasher models affected:</p> <ul style="list-style-type: none">• SB908WK• SB908SK• SB916WK• SB916SK• SB926SK <p>With serial numbers between 70700000 to 72400000. Sold after June 2007.</p> <p>The model and serial numbers can be found on the front right hand inner door panel.</p>
What to do	<p>Do not operate the dishwasher when unattended, or use the delayed start program. Switch it off at the power point when the cycle has been completed, until it has been checked.</p> <p>With the model and serial number handy call Westinghouse on 0800 277 542 to register your details, between 8.30am and 5.00pm Monday to Friday.</p> <p>Electrolux, the manufacturer of Westinghouse dishwashers, will arrange for a service technician to call free of charge.</p>
More Information	No recall notice was issued, refer to the link below: Consumer website

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.