

Fire Related Product Recall Notice



Date issued: 23 December 2013

Holden Captiva diesel-powered cars

Holden Australia has issued a recall of more than 14,000 diesel-powered **Holden Captiva 5** and **Captiva 7** models over a potential fire risk.

Problem

Some vehicles have a fuel feed hose that over time may rub against the air conditioning suction pipe. The fuel feed hose may wear, leading to a fuel leak and posing a potential fire hazard.

Details

Captiva 5 and Captiva 7 models built between 5 February 2011 and 2 November 2012, and fitted with the 2.2-litre turbo diesel four-cylinder engine.

VIN RANGE: KL3DD266JBB028825 - KL3CD266JCB092300

BUILD DATE RANGE: 05 FEBRUARY 2011 - 02 NOVEMBER 2012



What to do

Owners of affected Captiva models can expect a letter in the mail, encouraging them to contact their dealer for an inspection.

Contact

For more information contact Holden New Zealand on 0800 465 336 or visit your nearest Holden dealer.

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.