

Fire Related Product Recall Notice



Date issued: 02 July 2015

InSinkErator Waste Disposal unit

InSinkErator is undertaking a voluntary corrective action plan that affects some installations of certain models of disposers.

Problem

Due to improper installation or damage to the air switch, water may come into contact with the micro switch.

This poses a potential fire hazard.

Details

The following models of InSinkErator waste disposer are potentially affected : 55+ and 65+ where the serial number contains: N12, N13, N14, N1501, N1502 or N1503



What to do

See www.insinkeratorsafetynotice.com for assistance in determining whether you have an affected model, and for further information.

If you have an affected model, register to receive a replacement air switch. In the meantime, the disposer may be used normally, but should be disconnected from the power supply when not in use.

You will be provided with a replacement air switch and simple instructions as to how to fit the replacement. Further assistance will be provided by InSinkErator on a case-by-case basis.

Contact

For more information contact www.insinkeratorsafetynotice.com or contact Parex Industries Ltd on 0800 200 510 or email info@parex.co.nz

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.