

FIRE RELATED PRODUCT RECALL NOTIFICATION

LG side-by-side Fridges	
15 July 2011	ACTION - New Zealand recall
Problem	A switch in the ice dispenser of the fridge may deteriorate and malfunction, potentially resulting in a fire hazard.
Details	<p>The following models are affected:</p> <ul style="list-style-type: none">• GR-L207DTUA• GR-L207DVUA• GR-P207DTUA• GR-P207DVUA• GR-L207GTZ• GR-L247GTZ• GR-L207GVZ• GR-L207EQ• GR-P207 EQ• GR-L207NSUA• GR-L207MSZ• GR-L207MGZ• GR-P247MSZ <p>The model number can be located on the left hand wall inside the fridge door.</p> <p>Sold from 2002 to 2005 throughout New Zealand.</p>
What to do	Call 0800 665 010 to check your serial number, and if affected, arrange for a service technician to replace the micro switch.
More Information	Consumer website

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.