## New Zealand Fire Service Fire Research & Investigation Unit



## FIRE RELATED PRODUCT RECALL NOTIFICATION

Map-Pro, Propylene and MAPP gas cylinders	
22 March 2012 ACTION - New Zealand recall	
Problem	Due to a manufacturing defect complete shut-off of the cylinder valve may be delayed resulting in gas leakage. These leaks may pose a potential risk of fire or explosion.
Details	Map-Pro, Propylene and MAPP gas cylinders, with a batch code of 'W [month] D' through 'W [month] L' (no I-year). Batch codes can be found on base plate of cylinder.
What to do	If the cylinder has never been connected to a torch or other device, do not use cylinder. Return it to the place of purchase for a full refund or exchange.
	If the cylinder is currently connected to a torch or other device, do not disconnect it. Take the cylinder outdoors; ignite the torch and burn off the entire contents. Disconnect the torch from the empty cylinder and dispose per the instructions on the cylinder label OR return it to the place of purchase for a full refund or exchange.
	If the cylinder has been connected to a torch or other device but is not connected now, attach the torch, take the cylinder outdoors, ignite and burn off the entire contents. Disconnect torch from the empty cylinder and dispose per the instructions on the cylinder label OR return it to the place of purchase for a full refund or exchange.
	Never leave lit torch and cylinder unattended. Use torch only in a well-ventilated area.
More Information	Consumer website Call 0508 276 642 or email mapcylinderrecall@worthingtonindustries.com

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.