

## FIRE RELATED PRODUCT RECALL NOTIFICATION

Mechpro 2.5 Horsepower Air Compressor	
27 Oct 2011	ACTION - New Zealand recall
Problem	<p>The air compressor may short circuit and overheat due to a manufacturing defect.</p> <p>Overheating in the compressor motor could lead to a potential fire risk.</p>
Details	<p>Mechpro 2.5 horsepower direct drive compressor with 40 litre air tank, product number MP 2540.</p> <p>Sold through Repco stores nationwide from December 2009 to October 2011.</p>
What to do	<p>Stop using the air compressor immediately and ensure that it is disconnected from the power supply.</p> <p>Return it to the place purchased for a full refund.</p> <p><b><i>Please note this recall applies to all units, including those previously repaired or exchanged.</i></b></p> <p>Call 0800 645 654 for more information.</p>
More Information	<a href="#">Consumer website</a>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.