

Fire Related Product Recall Notice

Date issued: 04 November 2015



Nutriblend and NutrilInfusion

Brand Developers Limited has issued a recall of certain Nutriblend and NutrilInfusion models sold in New Zealand due to a potential fire hazard.

Problem

An internal component of the blender is made of unsuitable material. If spilled liquid enters the internal parts of the blender it has the potential to cause fire.

Details

The affected models have a Silver Stainless Steel Base, carry the model number XJ-13409 and were sold via the TV Shop and live events from March 2015 – September 2015.

Model numbers can be found on the label on the bottom of the blender.



NUTRiNFUSION

Blender Model No: XJ-13409
220-240V ~ 50Hz 700W



NUTRIBLEND

Blender Model No: XJ-13409
220-240V ~ 50Hz 700W



These are the only models effected by this recall.

What to do

If you have one of these models of Nutriblend or NutrilInfusion blenders, stop using the blender immediately and register your details online at www.nutrilinfusion.co.nz/recall or call 0800 101 346 for information on how to return the product for free repair free of charge.

Contact

For more information contact Brand Developers Limited at www.nutrilinfusion.co.nz/recall or call 0800 101 346.

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.