

FIRE RELATED PRODUCT RECALL NOTIFICATION

| PDL Powerguard RCDs | |
|-----------------------------|--|
| 25 February 2008 | |
| ACTION - New Zealand recall | |
| Problem | <p>The Residual Current Devices (RCDs) may not provide any protection against electric shock or fire in the event of an electrical fault in connected electrical equipment.</p> <p>Failure of the RCD to operate as intended may result in serious harm/electrocution and/or fire.</p> |
| Details | <p>PDL Powerguard RCDs with batch code 0507 (week 05 of 2007) sold nationally between March 2007 and January 2008.</p> <p>Affected items:</p> <ul style="list-style-type: none">• PDL Powerguard Vertical Switched Socket - PDL Cat: 691RCD30WH• PDL Powerguard Rewireable Cord-set - PDL Cat: 955RW; 953/15; 954; 955; 955/10; NT955BULK; 956 <p>The batch code is located under the removable clip-on cover plate of the vertical switched socket products, and on the side of the cord-set products.</p> |
| What to do | <p>If you identify the 0507 batch code, stop using the products and immediately seek advice from Schneider Electric NZ on 0800 735 326 between 8 am and 8 pm, or fax 0800 739 939, or email rcdsafety@nz.schneider-electric.com.</p> <p>Products from the 0507 batch code will be replaced free of charge. Instructions will be provided on how each product will be replaced.</p> <p>Note: no other PDL items are affected.</p> |
| More Information | <p>Refer to the links below:</p> <p>Recall notice</p> <p>Energy Safety article</p> <p>Consumer website</p> |

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.