

FIRE RELATED PRODUCT RECALL NOTIFICATION

| PDL Thermosafe Bathroom Heater | |
|---------------------------------------|--|
| 22 September 2010 | |
| ACTION - New Zealand recall | |
| Problem | In some instances the heater could overheat due to temperature rise in the terminal block. this could potentially cause damage to the plastic housing and could result in the risk of fire. |
| Details | <p>This recall effects The PDL 3208 Thermosafe installed after 1 July 2006.</p> <p>You can identify the heaters by the logo 'PDL Thermosafe' on the top of the heater. No other PDL items are affected.</p> |
| What to do | <p>If you have one of these heaters and believe it was installed after 1 July 2006, please discontinue use and register your details with Schneider Electric (NZ) Ltd by visiting the following website http://www.senz-quality.com/</p> <p>Alternatively you can contact Schneider Electric NZ Limited on 0508 256 256 for further information.</p> <p>You will be contacted by a company representative who will arrange for checking and replacement as necessary. This will be done at no cost to you.</p> <p>Do not remove the product or inspect it yourself.</p> |
| More Information | <p>Refer to the links below:</p> <p>Recall notice</p> <p>NZ Herald article</p> <p>Consumer website</p> <p>Schneider Electric (NZ) Ltd website</p> |

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.