

Fire Related Product Recall Notice

Date issued: 15 January 2014



Parmco freestanding gas stoves

Parmco has issued a recall of certain freestanding gas stoves sold in New Zealand due to a potential gas leak.

Problem

There is a cracked gas valve in some Parmco freestanding gas stoves sold between April and October 2013.

Details

The following models may be affected:

Model	Serial numbers		
AR600	306320013020001 - 0040 306320013030001 - 0080 306320013040039 - 0129		
AR600 – LEG	306820013030001 - 0036 306820013040001 - 0028 306820013040029 - 0068		
AR900	306420013030001 - 0060 306420013040001 - 0025 306420013040026 - 0067 306420013040069 - 0118		
AR900- LEG	306920013030001 - 0040 306920013020001 - 0030 306920013040001 - 0039		
AR900 – OBS	311820013040001 – 0025		



	∭ Pa	∰ parmco		
Model number:	AR 600	AR 600		
Type of gas:	Natural Gas	General Product LPG		
Burner pressure:	2 kPa	2.75 kPa	1	
Supply presure:	2.5 kPa max, 1.7 kPa min	3.5 kPa max, 2.5 kPa min	1	
Gas input rate:	30 MJ/h	26.6 MJ/h	1	
Electrical power:	240 V, 50Hz	240 V, 50Hz		
Serial number:	XXXXXXXXXXXXXXX	XXXXXXXXXXXXXX 4		
Supplier: Parmco Applia	ances, 519 Mt. Wellington Highway, A	uckland, New Zealand		
(CZ 927 MADE IN	PRC		

What to do

If you have one of these models check the serial number. The serial number is inside the slide out drawer or on the rear panel of the appliance, or with your operating manual.

If your stove has one of these serial numbers:

Contact Parmco immediately on 0800 727 626 or email safety@parmco.co.nz.

Check the stove for a gas smell, ensuring you have turned off all burners first. If you find a leak shut the unit off at the gas main.

Parmco will send a service technician to replace gas valves on all affected models free of charge.

Contact

For more information contact Parmco New Zealand on 0800 727 626

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.