

Fire Related Product Recall Notice



Date issued: 27 March 2017

Polaris Sportsman 1000 - model year 2015-2016

Polaris New Zealand has issued a recall of the above model over a potential fire risk.

Problem

The exhaust manifold side panel may contact the exhaust system causing the panel to melt. If contact is made, the exhaust panel poses a fire hazard.

Details

Affected models sold from 1 January 2016 - 22 March 2017

What to do

Consumers should contact their nearest dealer and arrange to have the manifold side panel replaced.

Contact

Polaris New Zealand

<http://www.polaris.co.nz/en-nz/atv-ranger-rzr/dealer-locator/find.html>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.