


Fire Related Product Recall Notice



Date issued: 12 January 2018

Saber Grills LP Regulators

Affected units sold at BBQ's & More and Lifestyle (in Christchurch) from October 2012



Problem

The grills' LP regulator can allow gas to flow at a higher pressure than intended, which can result in a gas leak and flame burst from the burner knobs, posing fire and burn hazards.

Details

Model RA329 LP regulators with date code in the range: 1120 to 1344.

Affected grills (sold with the LP regulator):

SABER® 330 LP Stainless Grill with model number R33SC0012

SABER® 500 LP Stainless Grill with model number R50SC0012

SABER® 670 LP Stainless Grill with model number R67SC0012

(model numbers can be found on the underside of the grease tray)

Affected conversion kits (sold/installed with the LP regulator):

SABER® Natural Gas to LP Conversion Kit with model number AOOAA0912

Kit, Control Console w/ HVR Assembly & Push Button Ignition, with model number 55710843

What to do

Stop using the recalled grills and regulators and contact BBQ's & More for a free repair kit with installation instructions.

A video on how to install the replacement components is also available on the supplier website.

Contact

BBQs & More

<http://www.bbqsandmore.co.nz/saber-grills-regulator-recall/>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, Fire and Emergency New Zealand does not guarantee the accuracy of it. Fire and Emergency New Zealand is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.