

## **FIRE RELATED PRODUCT RECALL NOTIFICATION**

| <b>Serene Bathroom Heaters</b> |   |
|--------------------------------|---|
| <b>05 November 2007</b>        | <b>ACTION - New Zealand recall</b>  |
| Problem                        | The fan motor may stop, causing the heater to catch fire.   |
| Details                        | Serene brand plastic bathroom heaters models S1088 (chrome) and S1077 (white) with serial prefix HB only.<br><br>Sold after 25 March 2007.  |
| What to do                     | Do not use the heater. Disconnect it from the power supply.<br><br>Only Serene S1077 and S1088 bathroom fan heaters with serial number prefix HB are affected by this recall.<br>Contact the original supplier or Energy Safety at:<br>Worksafe New Zealand<br>86 Customhouse Quay<br>PO Box 165<br>Wellington 6140<br>New Zealand<br><br>Free-phone (NZ only): 0800 030 040<br>International: +64-3-962 6248 |
| More Information               |   |

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.