## **New Zealand Fire Service Fire Research & Investigation Unit**



## FIRE RELATED PRODUCT RECALL NOTIFICATION

Sony Lithium Ion Laptop Batteries	
03 Novembe	er 2008 ACTION - New Zealand recall
Problem	It is possible for the batteries to overheat, which could pose a risk of fire.
Details	Sony 2.15Ah Lithium Ion batteries used in Hewlett-Packard, Toshiba and Dell notebook computers. Lists of affected models and details on how to check your laptop's serial number can be found at:  • Hewlett-Packard - <a href="http://bpr.hpordercenter.com/hbpr/">http://bpr.hpordercenter.com/hbpr/</a> • Toshiba - <a href="http://www.csd.toshiba.com/cgi-bin/tais/support/jsp/bulletin.jsp?soid=1501060">http://www.dellbatteryprogram.com/</a> • Dell - <a href="http://www.dellbatteryprogram.com/">http://www.dellbatteryprogram.com/</a>
What to do	Immediately remove the recalled battery from the computer, and request a free replacement battery through the company's website. After removing the recalled battery, the AC adapter can be used to power the computer until a replacement battery arrives.
More Information	No recall notice was issued, refer to the links above or:  Consumer website