

Fire Related Product Recall Notice



Date issued: 29 March 2017

Stihl MS 461 and GS 461 chainsaws

Stihl has issued a recall of the above models over a potential fire risk.

Problem

The fuel line can leak, posing fire and burn hazards.

Details

MS 461 - Z

GS 461 - Z

machine serial numbers between #173 092 800 - #181 993 952.

What to do

Stop using the recalled chainsaws and return them to an authorized STIHL dealer for a free inspection and free repair.

Contact

Stihl Limited

info@stihl.co.nz

<http://www.stihl.co.nz/>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.