


FIRE RELATED PRODUCT RECALL NOTIFICATION

Sunbeam Rechargeable SM8700 StickMaster Blender	
08 March 2013	ACTION - New Zealand recall
Problem	In rare cases the internal lithium-ion rechargeable battery may overheat causing a potential fire hazard.
Details	<p>The following products are affected:</p> <ul style="list-style-type: none">• Sunbeam (Rechargeable) SM8700 StickMaster Cordless Stick Blenders sold since July 2011. <p>No other Sunbeam Stick Blenders are affected by this recall.</p> <p>The model number of affected products can be found on the charging base and hand piece as pictured at the bottom of this notice.</p>
What to do	Stop using the product, unplug the charging base from the power socket and call 0800 252 653 to order a replacement.
More Information	Recall notice Sunbeam website Or call 0800 252 653.

Location of stickers identifying product model number



Charging Base



Hand Piece

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.