



FIRE RELATED PRODUCT RECALL NOTIFICATION

Sunbeam Regency and Ralta Electric Blankets	
27 August 2012 ACTION - New Zealand recall	
Problem	The cord of the electric blankets may fatigue in the area of the detachable connector resulting in a potential short circuit and fire hazard.
Details	<p>The following products are affected:</p> <ul style="list-style-type: none">• Sunbeam Regency electric blankets, model numbers BA442R, BA445R and BA447R. Sold at Farmers stores from 2010 to 2012.• Sunbeam Ralta electric blankets, model numbers BA201, BA203 and BA208. Sold through retailers nationwide from 2010 to 2012. <p>Model numbers can be found on the care label sewn into the blanket.</p> <p>Affected models can be identified by the part number BL0215 moulded on the back of the detachable controller.</p>
What to do	Stop using the electric blanket and visit www.sunbeam.co.nz/recall to check if your model is affected and arrange a free replacement product.
More Information	<p>Recall notice Consumer website</p> <p>Or call 0800 252 653.</p>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.