

# Fire Related Product Recall Notice

Date issued: 5 July 2017



## Wismec Exo Skeleton for ES300 personal vaporizers

### Availability

2 units are confirmed as having caught fire in New Zealand.

If you have purchased the mod at another store/online, you should consider stopping use and contacting your supplier for a remedy.

### Problem

The 510 connector between the atomiser and the body is not properly sealed.

Juice can leak through the 510 connectors may cause battery venting and fires.



### Details

Wismec ES300 300W Mod

Sold at Hawkes Bay Vapour stores from the 11th to 27th June 2017

### What to do

Stop using the Wismec Exo Skeleton for the ES300 and remove the atomisers and all batteries.

Return the device to the store you purchased it from for a full refund or replacement.

### Contact

Hawkes Bay Vapour

<mailto:sales@hbvapour.nz> - tel:0508 827 687

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever.