


Fire Related Product Recall Notice



Date issued: 12 February 2018

Lenovo - ThinkPad X1 Carbon 5th Generation

Potentially affected units sold from December 2016 to October 2017



Problem

A loose screw can damage and compromise the battery.

If the battery is compromised, it may pose a fire hazard.

Details

ThinkPad X1 Carbon 5th Generation laptops

Affected Machine Types: 20HQ, 20HR, 20K3, 20K4

Affected Dates of manufacture:

16/12, 17/01, 17/02, 17/03, 17/04, 17/05, 17/06, 17/07, 17/08, 17/09, 17/10

What to do

Click the 'visit their site' link below, to see if your laptop is affected.

If the laptop is included in the recall, use the website to organise an inspection and repair.

Contact

Lenovo (Australia & New Zealand) Pty Ltd

tel:0800 787 806

https://support.lenovo.com/X1C_5GEN_RECALL

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, Fire and Emergency New Zealand does not guarantee the accuracy of it. Fire and Emergency New Zealand is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.