

FIRE RELATED PRODUCT RECALL NOTIFICATION

Belkin Tune Base iPhone/iPod Car Kits	
09 November 2009 ACTION - New Zealand recall	
Problem	Under conditions of heat, humidity or prolonged connection to a power supply, the car kits may overheat and short circuit potentially resulting in fire.
Details	<p>The following products purchased on or after 1 April 2009 are affected:</p> <ul style="list-style-type: none">• TuneBase Direct with Hands-Free, model number F8Z441 (also known as F8Z441au)• TuneBase FM with Hands-Free, model number F8Z442• TuneBase FM with ClearScan, model number F8Z176 <p>The model number is located on the back of each product.</p>
What to do	Stop using the car kit. Contact 0800 445 844 or visit http://www.belkin.com/support/tunebase/exchange/info.aspx?cid=100&lid=1www.belkin.com%20 to arrange a replacement model, free of charge.
More Information	No recall notice was issued, refer to the link above or: Consumer website

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.