

FIRE RELATED PRODUCT RECALL NOTIFICATION

Dick Smith Portable DVD/Media Players	
10 January 2013	ACTION - New Zealand recall
Problem	<p>In rare cases the internal lithium-ion rechargeable battery may overheat.</p> <p>Overheating batteries are a potential fire hazard.</p>
Details	<p>This recall involves:</p> <p>Dick Smith 7" Portable DVD Media player Cat# D6200 Dick Smith 7" Portable DVD Media player Cat# D6201 Dick Smith 9" Portable DVD Media player Cat# D6203 Dick Smith 7" Portable DVD player Cat# GE4203</p> <p>These products have been sold in Dick Smith stores in Australia and New Zealand from November 2009 to July 2012.</p> <p>Once removed from the packaging the item can be identified by the Dick Smith logo below the screen for the D6200, D6201, and D6203 and on the top lid of the GE4203. The Catalogue No. can be found on the rear or base of the unit.</p>
What to do	<p>Customers should not use these products.</p> <p>Customers are asked to immediately return the products to any Dick Smith store for a full refund or phone 0800 373 347 (option 1) for more information.</p>
More Information	<p>Recall Notice Dick Smith website</p>



This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.