

## FIRE RELATED PRODUCT RECALL NOTIFICATION

Drybar Heated Clothes Racks	
<b>17 August 2010</b> <i>(updated January 2011)</i> <b>ACTION - New Zealand recall</b>	
Problem	Due to a manufacturing fault the electrical insulation of the clothes rack may fail, leading to a risk of fire.
Details	Drybars heated clothes rack, batch numbers 912, 917, 921 and 932. The batch number can be located on the back of the control box. Sold at The Heated Clothes Rack Company, Mitre 10, Bunnings, Designer Direct stores and selected home shows.
What to do	<p>The Heated Clothes Rack Company has gone into liquidation and can no longer provide refunds, repairs or replacements.</p> <p>To register a claim against the company, please contact the liquidator Rod McKenzie, PO Box 12165, Palmerston North 4444.</p> <p><b>Note, a prohibition notice has been issued so this product can no longer be sold, offered for sale, or used.</b></p> <p>It is suggested that if you have one of these units that you cut the power cord from the Drybars unit so that it can be used as a non-heated clothes rack only.</p>
More Information	Refer to the links below: <a href="#">Recall notice</a> <i>note refund information on this notice is no longer relevant</i> <a href="#">Energy Safety Service article</a> <a href="#">Prohibition Notice</a>

*This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.*