

Fire Related Product Recall Notice



Date issued: 29 July 2014

Goldair Bathroom Fan Heaters

Goldair has issued a recall on two models of Bathroom Fan Heaters sold and installed in New Zealand.

Worksafe NZ has issued a prohibition notice which applies to the use and sale of these units. Click here to view the [media](#) release

Problem

The product is being prohibited in New Zealand due to risk of fire. This has led to several house fires

Details

The affected Goldair Bathroom fan Heaters are identified by the model number on the back of the unit. The Model numbers affected are 3108 and 3109



What to do

Consumers should immediately stop using the heater.
Turn the heater off and contact Goldair on 0800 232 633 or a registered electrician.

Contact

For more information contact Goldair on 0800 232 633 between 8 am -5pm Monday-Friday or email recall@goldair.co.nz

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.