

Fire Related Product Recall Notice



Date issued: 28 March 2017

Lexus CT200h, HS250h, Model years 2009/15

Lexus has issued a recall of the above models over a potential fire risk.

Problem

Subject vehicles are equipped with a fuel evaporative emission control unit (canister) assembled to the fuel tank.

There is a possibility that the canister could develop a crack, which overtime could expand and eventually fuel may leak from the crack when the vehicle has a full tank of gas. Fuel or fuel vapour in the presence of an ignition source could increase the risk of a vehicle fire.

Details

Lexus CT200h, HS250h, Model years 2009-2015

What to do

Contact your nearest authorised Lexus Dealer to arrange a convenient time to have the repairs completed.

Alternatively, contact Lexus New Zealand to discuss.

Contact

oncall@lexus.co.nz

<http://www.lexus.co.nz/>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.