

Fire Related Product Recall Notice

Date issued: 02 July 2015



Refurbished iPhone® and iPad® Chargers

EB Games are recalling Refurbished iPhone® and iPad® Chargers sold nationwide from 25 July 2014 to 28 May 2015.

Problem

The charger may malfunction resulting in damage to the charger.



Details

A malfunction of the charger may cause a 'popping' noise followed by smoke and a burning smell.

Only refurbished chargers are affected by this recall notice

What to do

Customers should immediately stop using your charger and return it to any EB games store to receive a free replacement

Contact

For more information contact EB games online www.ebgames.co.nz or on 0800EBGames or email websales.contact.nz@ebgames.com

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising