

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3056182	9/08/2020 22:33:56	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3056199	10/08/2020 1:00:56	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Extended beyond structure of origin
F3057568	12/08/2020 0:45:17	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3060827	17/08/2020 20:27:35	Far North District	Structure fire with no damage	Ceiling and roof assembly	Failure to clean	Not Recorded
F3063501	22/08/2020 21:06:30	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3065019	25/08/2020 19:51:47	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to part of room or area of origin
F3068134	31/08/2020 14:51:50	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3068382	31/08/2020 21:41:37	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3069355	2/09/2020 14:24:20	Buller District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3070488	4/09/2020 13:05:24	Whanganui District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3070687	4/09/2020 20:55:21	Rangitikei District	Structure fire with no damage	Ceiling and floor assembly	Unable to classify	Not Recorded
F3074577	11/09/2020 9:43:46	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3075392	12/09/2020 15:05:04	Auckland	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Extended beyond structure of origin
F3076021	13/09/2020 21:12:30	Wellington City	Structure fire with damage	Ceiling and roof assembly	Failure to use ordinary care	Confined to object of origin
F3084257	26/09/2020 19:43:55	Napier City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3087510	1/10/2020 16:05:27	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3087877	2/10/2020 10:30:11	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3090322	6/10/2020 0:44:41	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Equipment overloaded	Confined to part of room or area of origin
F3091621	7/10/2020 17:25:24	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3092470	8/10/2020 20:32:23	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3094014	11/10/2020 12:21:12	Kawerau District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3095522	13/10/2020 20:29:40	Whakatane District	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to floor of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3095903	14/10/2020 5:12:19	Auckland	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3096062	14/10/2020 10:31:25	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to object of origin
F3098641	17/10/2020 15:50:24	Tararua District	Structure fire with no damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Not Recorded
F3100670	20/10/2020 21:51:36	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to object of origin
F3105539	28/10/2020 5:30:08	Stratford District	Structure fire with damage	Ceiling and floor assembly	Unable to classify	Confined to part of room or area of origin
F3108473	1/11/2020 8:46:49	Auckland	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to floor of origin
F3110032	3/11/2020 15:40:30	Tauranga City	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to fire cell of origin
F3112594	6/11/2020 23:51:27	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3117528	13/11/2020 12:25:52	Wellington City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to room of origin
F3118631	14/11/2020 22:49:22	Auckland	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to object of origin
F3123357	21/11/2020 14:46:08	Nelson City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to object of origin
F3124318	23/11/2020 9:15:36	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to structure of origin
F3129936	1/12/2020 10:21:04	Cromwell	Structure fire with damage	Ceiling and floor assembly	Unable to classify	Confined to object of origin
F3133700	6/12/2020 16:35:37	Far North District	Structure fire with damage	Ceiling and roof assembly	Animal	Extended beyond structure of origin
F3133700	6/12/2020 16:35:37	Far North District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Extended beyond structure of origin
F3142701	18/12/2020 11:33:37	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3143257	19/12/2020 2:12:10	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to object of origin
F3145132	21/12/2020 21:56:48	South Waikato District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3145139	21/12/2020 22:23:39	Whanganui District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3145514	22/12/2020 12:25:55	Auckland	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3146024	22/12/2020 22:26:34	Invercargill City	Structure fire with damage	Ceiling and floor assembly	Undetermined	Confined to structure of origin
F3152059	1/01/2021 13:34:16	South Waikato District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3152772	2/01/2021 17:34:31	Auckland	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3152898	2/01/2021 21:28:04	Westland District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Extended beyond structure of origin
F3156325	9/01/2021 17:16:52	Thames-Coromandel District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Extended beyond structure of origin
F3156574	10/01/2021 6:44:51	Tasman District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3160726	16/01/2021 19:25:16	Southland District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3163892	21/01/2021 14:41:02	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3164151	22/01/2021 1:46:22	Napier City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to object of origin
F3166735	26/01/2021 11:44:53	Ruapehu District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F3168888	29/01/2021 9:22:47	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3170556	1/02/2021 0:00:18	Queenstown-Lakes District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3176679	9/02/2021 22:08:38	Hurunui District	Structure fire with no damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Not Recorded
F3176692	9/02/2021 22:50:57	Gisborne District	Structure fire with damage	Ceiling and floor assembly	Rekindled from previous fire, Re-ignition	No damage of this type
F3176743	10/02/2021 1:13:31	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	No damage of this type
F3182932	18/02/2021 20:25:22	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3188555	26/02/2021 10:22:24	Clutha District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to object of origin
F3189715	27/02/2021 21:28:15	Kaipara District	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to part of room or area of origin
F3189814	28/02/2021 3:10:12	Kaipara District	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F3191003	2/03/2021 1:00:23	Western Bay of Plenty District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3195414	8/03/2021 18:27:51	Grey District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to part of room or area of origin
F3201986	17/03/2021 16:35:41	Whangarei District	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F3203833	19/03/2021 17:22:13	Auckland	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to part of room or area of origin
F3203907	19/03/2021 19:31:18	Dunedin City	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3204615	20/03/2021 20:23:42	Waipa District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3206874	23/03/2021 16:22:04	Whangarei District	Structure fire with damage	Ceiling and floor assembly	Design deficiency	Confined to room of origin
F3207231	23/03/2021 23:54:14	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3207535	24/03/2021 10:33:08	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3208193	25/03/2021 7:35:54	Masterton District	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F3215058	3/04/2021 18:18:19	Hamilton City	Structure fire with no damage	Ceiling and roof assembly	Heat source too close to combustibles	Not Recorded
F3223758	16/04/2021 3:42:08	Kaipara District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3228253	23/04/2021 3:54:01	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3229057	24/04/2021 10:34:40	Auckland	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to room of origin
F3229882	25/04/2021 21:32:34	Kapiti Coast District	Structure fire with no damage	Ceiling and floor assembly	Part failure, leak or break	Not Recorded
F3236828	6/05/2021 0:41:50	Timaru District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to structure of origin
F3236834	6/05/2021 1:55:59	Hamilton City	Structure fire with damage	Ceiling and floor assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3238184	7/05/2021 17:25:37	Christchurch	Structure fire with damage	Ceiling and roof assembly	Legality not known	Confined to structure of origin
F3243398	14/05/2021 19:47:46	Balclutha	Structure fire with no damage	Ceiling and roof assembly	Short circuit, earth fault	Not Recorded
F3245139	17/05/2021 21:59:38	Coromandel	Structure fire with no damage	Ceiling and roof assembly	Carelessness with heat source - Other	Not Recorded
F3246732	20/05/2021 5:29:53	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3249903	25/05/2021 1:11:45	Ngatea	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to structure of origin
F3257377	3/06/2021 19:32:08	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3259468	7/06/2021 17:25:42	Clutha District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3262306	11/06/2021 20:42:16	Tasman District	Structure fire with no damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Not Recorded
F3262534	12/06/2021 11:34:11	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Careless disposal or use: cigarettes, ashes, embers	Confined to fire cell of origin
F3262809	12/06/2021 19:37:02	Gore District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3263893	14/06/2021 18:55:27	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to fire cell of origin
F3265105	16/06/2021 14:19:45	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3265399	16/06/2021 21:17:47	Wellington City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3267541	20/06/2021 3:17:42	Auckland	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to structure of origin
F3273629	28/06/2021 20:21:17	Waikato District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3276951	3/07/2021 15:44:58	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to object of origin
F3278477	5/07/2021 20:55:36	Timaru District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3280481	8/07/2021 15:49:53	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to object of origin
F3283260	12/07/2021 18:58:02	Fordell	Structure fire with no damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Not Recorded
F3283327	12/07/2021 20:05:00	Auckland	Structure fire with damage	Ceiling and roof assembly	Careless disposal or use: cigarettes, ashes, embers	Confined to structure of origin
F3285169	15/07/2021 11:44:52	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3285636	16/07/2021 3:43:49	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3290581	22/07/2021 2:44:53	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3293176	26/07/2021 14:22:50	Napier	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin
F3294844	29/07/2021 6:53:32	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F3295188	29/07/2021 14:35:10	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3298463	3/08/2021 17:47:01	Horowhenua District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to structure of origin
F3300202	6/08/2021 13:48:30	Auckland	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F3304304	12/08/2021 22:07:09	Auckland	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3307432	18/08/2021 9:43:53	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3307523	18/08/2021 13:41:39	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to object of origin
F3310559	26/08/2021 17:29:54	Auckland	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to fire cell of origin



# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3312492	31/08/2021 16:05:57	Palmerston North City	Structure fire with no damage	Ceiling and roof assembly	Exposure fire	Not Recorded
F3312645	1/09/2021 4:08:00	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to structure of origin
F3312889	1/09/2021 14:58:03	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3313573	3/09/2021 9:09:27	Auckland	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F3318779	13/09/2021 4:20:29	Ranfurly	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3319046	13/09/2021 11:32:29	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3323092	19/09/2021 14:45:17	Rangitikei District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3326533	25/09/2021 10:40:49	Porirua City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3328889	28/09/2021 17:15:32	Taupo District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to floor of origin
F3331126	1/10/2021 21:43:46	Clutha District	Structure fire with no damage	Ceiling and roof assembly	Operating deficiency - not classified above	Not Recorded
F3333648	5/10/2021 20:34:26	Auckland	Structure fire with damage	Ceiling and floor assembly	Installation deficiency	Confined to structure of origin
F3334418	6/10/2021 19:05:07	Mackenzie District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin
F3335039	7/10/2021 22:39:12	Napier City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3335106	8/10/2021 7:22:35	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3335701	9/10/2021 7:43:08	Auckland	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3340152	16/10/2021 15:57:38	New Plymouth District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3343362	21/10/2021 20:53:12	Auckland	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F3345204	24/10/2021 21:02:39	Christchurch City	Structure fire with damage	Ceiling and floor assembly	Part failure, leak or break	Confined to part of room or area of origin
F3347870	28/10/2021 16:17:27	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Failure to use ordinary care	Confined to floor of origin
F3348981	30/10/2021 11:49:47	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3353520	5/11/2021 21:52:54	Wellington City	Structure fire with no damage	Ceiling and roof assembly	Reckless with fireworks	Not Recorded
F3354218	7/11/2021 7:52:03	Southland District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3355408	8/11/2021 20:50:52	Queenstown-Lakes District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to structure of origin
F3355500	9/11/2021 6:00:29	Palmerston North City	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F3356618	10/11/2021 12:14:14	Palmerston North City	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to structure of origin
F3358261	12/11/2021 13:27:52	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3361611	17/11/2021 20:57:56	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Spontaneous ignition	Extended beyond structure of origin
F3366300	24/11/2021 18:33:28	Taupo District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3370536	30/11/2021 18:47:56	Auckland	Structure fire with no damage	Ceiling and roof assembly	Short circuit, earth fault	Not Recorded
F3372747	4/12/2021 1:46:02	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Extended beyond structure of origin
F3373681	5/12/2021 17:42:04	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3377599	10/12/2021 23:23:01	Upper Hutt City	Structure fire with no damage	Ceiling and roof assembly	Failure to use ordinary care	Not Recorded
F3377921	11/12/2021 13:18:39	Otorohanga District	Structure fire with damage	Ceiling and roof assembly	Failure to clean	Confined to room of origin
F3385966	22/12/2021 13:48:45	Christchurch City	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to structure of origin
F3387947	25/12/2021 6:41:26	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3388646	25/12/2021 18:05:41	Auckland	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F3391572	31/12/2021 10:49:37	Rotorua District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F3392636	1/01/2022 14:53:15	Auckland	Structure fire with damage	Ceiling and roof assembly	Carelessness with heat source - Other	Confined to part of room or area of origin
F3393117	2/01/2022 11:39:28	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Extended beyond structure of origin
F3393344	2/01/2022 17:23:10	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3395374	5/01/2022 23:17:56	Far North District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3396813	8/01/2022 16:05:23	Tasman District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3397757	10/01/2022 11:47:35	Auckland	Structure fire with damage	Ceiling and roof assembly	Carelessness with heat source - Other	Confined to floor of origin
F3401870	16/01/2022 19:19:05	Pukekohe	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Extended beyond structure of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3402617	17/01/2022 21:04:59	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to room of origin
F3403385	18/01/2022 21:39:25	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	No damage of this type
F3405138	21/01/2022 10:59:44	Selwyn District	Structure fire with damage	Ceiling and floor assembly	Equipment overloaded	Extended beyond structure of origin
F3409770	28/01/2022 9:51:59	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3411587	30/01/2022 22:51:58	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3417806	9/02/2022 11:59:05	Auckland	Structure fire with damage	Ceiling and roof assembly	Construction deficiency	Confined to part of room or area of origin
F3430161	24/02/2022 14:07:03	Auckland	Structure fire with damage	Ceiling and roof assembly	Carelessness with heat source - Other	Confined to structure of origin
F3435414	4/03/2022 17:47:54	Timaru District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F3436272	6/03/2022 9:55:32	Palmerston North City	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F3436443	6/03/2022 14:21:29	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3436577	6/03/2022 18:19:59	Kaipara District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3436601	6/03/2022 19:44:40	Auckland	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F3440069	12/03/2022 1:37:21	Whanganui District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3441844	15/03/2022 3:17:08	Far North District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to room of origin
F3447877	22/03/2022 22:03:08	Porirua City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3448039	23/03/2022 7:46:19	Porirua City	Structure fire with damage	Ceiling and roof assembly	Lightning	Confined to part of room or area of origin
F3448800	24/03/2022 8:29:02	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3451591	28/03/2022 21:12:14	Kaipara District	Structure fire with no damage	Ceiling and roof assembly	Heat source too close to combustibles	Not Recorded
F3453047	30/03/2022 20:50:53	Thames-Coromandel District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3454100	1/04/2022 11:51:00	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3454498	1/04/2022 23:27:20	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3456444	4/04/2022 19:54:45	Auckland	Structure fire with no damage	Ceiling and floor assembly	Undetermined	Not Recorded



# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3457217	6/04/2022 5:41:55	Whanganui District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3459640	9/04/2022 19:49:39	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to floor of origin
F3461008	11/04/2022 14:34:08	Hurunui District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3461518	12/04/2022 10:04:14	New Plymouth District	Structure fire with damage	Ceiling and floor assembly	Short circuit, earth fault	Confined to structure of origin
F3464812	17/04/2022 7:41:22	Auckland	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to object of origin
F3466520	20/04/2022 5:49:19	Paihia	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3467973	22/04/2022 6:14:56	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to floor of origin
F3468916	23/04/2022 21:01:21	Waipa District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3469100	24/04/2022 9:10:50	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3469794	25/04/2022 16:30:58	Palmerston North City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3472121	28/04/2022 21:29:18	Rangitikei District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3474035	2/05/2022 7:47:50	Timaru District	Structure fire with no damage	Ceiling and roof assembly	Animal	Not Recorded
F3475356	3/05/2022 21:17:42	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3481011	12/05/2022 2:55:49	Buller District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3482460	13/05/2022 18:54:01	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to floor of origin
F3482616	14/05/2022 3:07:10	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3483576	15/05/2022 17:20:50	Tasman District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3485213	17/05/2022 23:51:17	Auckland	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to structure of origin
F3487998	21/05/2022 17:53:39	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to structure of origin
F3489366	24/05/2022 7:45:38	Nelson City	Structure fire with no damage	Ceiling and floor assembly	Unable to classify	Not Recorded
F3494690	31/05/2022 11:56:23	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3495574	1/06/2022 13:30:21	Hastings District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3496592	3/06/2022 7:05:15	Taupo District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3497062	3/06/2022 19:37:07	Christchurch City	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3500149	9/06/2022 9:50:38	Omakau	Structure fire with damage	Ceiling and roof assembly	Equipment not being operated properly	Confined to object of origin
F3500605	9/06/2022 22:15:57	New Plymouth District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3502242	12/06/2022 18:50:17	Wellington City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3506520	18/06/2022 21:19:51	Hastings District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to floor of origin
F3507466	20/06/2022 17:23:32	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to object of origin
F3507660	21/06/2022 4:43:31	Waitaki District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3509032	22/06/2022 16:09:51	South Wairarapa District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3509874	23/06/2022 19:09:01	Waikato District	Structure fire with no damage	Ceiling and roof assembly	Combustible placed too close to heat source	Not Recorded
F3515079	2/07/2022 17:50:33	Manawatu District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3525186	19/07/2022 4:10:48	Auckland	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to room of origin
F3527164	21/07/2022 19:07:06	Grey District	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to object of origin
F3536875	6/08/2022 15:59:58	Auckland	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3536977	6/08/2022 19:36:15	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3545026	19/08/2022 15:06:15	Hurunui District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3553463	2/09/2022 14:46:39	Queenstown-Lakes District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3555174	5/09/2022 22:59:29	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Pyrophoric	Confined to room of origin
F3555876	6/09/2022 22:18:20	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to object of origin
F3555876	6/09/2022 22:18:20	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Extended beyond structure of origin
F3556381	7/09/2022 15:04:31	Manawatu District	Structure fire with damage	Ceiling and roof assembly	Collision, overturn, knockdown	Confined to part of room or area of origin
F3557868	9/09/2022 20:58:15	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to floor of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3558505	11/09/2022 8:54:03	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F3559215	12/09/2022 14:42:03	Wellington City	Structure fire with no damage	Ceiling and floor assembly	Friction (sparks etc.)	Not Recorded
F3560456	14/09/2022 12:26:31	Palmerston North City	Structure fire with damage	Ceiling and floor assembly	Short circuit, earth fault	Confined to structure of origin
F3561492	15/09/2022 22:54:00	Tasman District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3562774	18/09/2022 3:45:38	Auckland	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to room of origin
F3564959	21/09/2022 13:02:23	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3566272	23/09/2022 13:50:43	Wellington City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3566488	23/09/2022 20:50:14	Carterton District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin
F3567879	26/09/2022 19:55:58	Tasman District	Structure fire with no damage	Ceiling and roof assembly	Short circuit, earth fault	Not Recorded
F3568905	28/09/2022 10:59:21	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F3570462	30/09/2022 20:47:10	South Wairarapa District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin
F3573843	7/10/2022 1:39:11	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3575699	10/10/2022 10:45:06	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3577480	13/10/2022 4:10:44	Auckland	Structure fire with damage	Ceiling and floor assembly	Short circuit, earth fault	Extended beyond structure of origin
F3579252	16/10/2022 5:17:09	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3583299	22/10/2022 20:54:45	Tasman District	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F3583332	22/10/2022 21:47:55	Tararua District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to object of origin
F3587610	29/10/2022 18:06:38	Queenstown	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3598778	13/11/2022 15:54:09	Kapiti Coast District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3604615	21/11/2022 17:30:18	Auckland	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Extended beyond structure of origin
F3606399	23/11/2022 17:38:26	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3613758	4/12/2022 11:10:10	Auckland	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to floor of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3621626	14/12/2022 15:37:43	Waimate District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to structure of origin
F3622537	15/12/2022 18:37:18	Kaikoura District	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to floor of origin
F3626118	20/12/2022 22:20:12	Ashburton District	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F3626359	21/12/2022 10:16:03	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3626849	22/12/2022 1:15:11	Central Otago District	Structure fire with damage	Ceiling and floor assembly	Spontaneous ignition	Confined to structure of origin
F3626961	22/12/2022 8:31:03	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3627515	23/12/2022 5:00:54	Auckland	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3630648	27/12/2022 17:50:41	Far North District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3635506	4/01/2023 13:48:17	Auckland	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3636276	6/01/2023 0:28:19	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to part of room or area of origin
F3638533	10/01/2023 0:26:35	Auckland	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F3639890	11/01/2023 17:50:44	Auckland	Structure fire with no damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Not Recorded
F3642808	16/01/2023 13:39:32	New Plymouth District	Structure fire with damage	Ceiling and roof assembly	Carelessness with heat source - Other	Confined to part of room or area of origin
F3643258	17/01/2023 4:15:43	Whakatane District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3643290	17/01/2023 7:25:56	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3644412	18/01/2023 13:52:23	Waikato District	Structure fire with no damage	Ceiling and roof assembly	Carelessness with heat source - Other	Not Recorded
F3646349	21/01/2023 5:37:06	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to part of room or area of origin
F3646479	21/01/2023 10:50:52	Westland District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to object of origin
F3646847	21/01/2023 22:48:12	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3648462	24/01/2023 11:12:49	Southland District	Structure fire with damage	Ceiling and roof assembly	Failure to use ordinary care	Confined to structure of origin
F3650577	27/01/2023 1:46:45	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3653266	27/01/2023 22:14:55	Waikato District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3653615	28/01/2023 4:35:28	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to fire cell of origin
F3657983	2/02/2023 10:42:10	Auckland	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to object of origin
F3665997	13/02/2023 4:25:38	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3666012	13/02/2023 5:08:03	Carterton District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3666796	13/02/2023 15:33:20	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3667182	13/02/2023 18:41:17	Auckland	Structure fire with no damage	Ceiling and floor assembly	Short circuit, earth fault	Not Recorded
F3667940	13/02/2023 22:46:46	Kaipara District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3670810	14/02/2023 17:34:33	Kaipara District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3674232	17/02/2023 20:25:03	Kapiti Coast District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3676184	20/02/2023 12:05:00	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3677499	21/02/2023 17:48:43	Auckland	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to object of origin
F3677826	22/02/2023 6:10:52	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to object of origin
F3681261	26/02/2023 10:45:22	Tauranga City	Structure fire with no damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Not Recorded
F3687105	5/03/2023 1:35:08	Rotorua District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to structure of origin
F3687493	5/03/2023 17:42:21	Napier City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3687833	6/03/2023 9:25:40	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3688451	6/03/2023 21:05:52	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3691112	10/03/2023 7:45:18	Whanganui District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3692464	11/03/2023 18:27:15	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to floor of origin
F3694648	14/03/2023 13:50:20	Waitomo District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3698962	20/03/2023 6:10:42	Palmerston North City	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to structure of origin
F3706636	29/03/2023 14:57:45	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin



# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3707179	30/03/2023 9:45:48	Selwyn District	Structure fire with no damage	Ceiling and floor assembly	Other electrical failure	Not Recorded
F3713042	6/04/2023 17:27:46	Auckland	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3713448	7/04/2023 12:18:29	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3713782	7/04/2023 22:15:29	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3724164	22/04/2023 23:22:05	Porirua City	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F3725965	26/04/2023 4:49:50	South Waikato District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3727418	28/04/2023 1:13:59	Porirua City	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3733027	5/05/2023 15:54:58	Tasman District	Structure fire with damage	Ceiling and roof assembly	Design deficiency	Confined to part of room or area of origin
F3733833	7/05/2023 0:59:27	Auckland	Structure fire with no damage	Ceiling and roof assembly	Installation deficiency	Not Recorded
F3734258	7/05/2023 20:26:28	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to fire cell of origin
F3738536	12/05/2023 14:47:59	Waimate District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3738817	13/05/2023 2:07:35	Nelson City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3738853	13/05/2023 4:45:38	Manawatu District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3739015	13/05/2023 11:05:07	Manawatu District	Structure fire with damage	Ceiling and floor assembly	Rekindled from previous fire, Re-ignition	Confined to object of origin
F3739166	13/05/2023 14:25:46	Tauranga City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F3741052	16/05/2023 5:50:15	Nelson City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to part of room or area of origin
F3743090	18/05/2023 11:12:57	Masterton District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3750091	28/05/2023 1:40:04	Auckland	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3751879	30/05/2023 16:31:59	Waipa District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to fire cell of origin
F3754361	2/06/2023 21:26:05	Hamilton	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to fire cell of origin
F3754889	3/06/2023 17:47:03	Wellington City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3756021	5/06/2023 18:54:10	Kapiti Coast District	Structure fire with damage	Ceiling and roof assembly	Design deficiency	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3758220	8/06/2023 15:44:23	Nelson City	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F3761217	13/06/2023 9:10:34	Queenstown-Lakes District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3762618	14/06/2023 17:59:39	Waimate District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3766818	20/06/2023 18:18:17	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3768444	23/06/2023 5:10:25	Auckland	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to structure of origin
F3775154	4/07/2023 14:22:43	South Taranaki District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3775375	4/07/2023 21:19:21	South Taranaki District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F3776085	5/07/2023 21:26:55	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3776754	6/07/2023 21:15:32	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F3778440	10/07/2023 7:23:54	Horowhenua District	Structure fire with no damage	Ceiling and roof assembly	Operating deficiency - not classified above	Not Recorded
F3779391	11/07/2023 13:06:12	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to floor of origin
F3779578	11/07/2023 19:16:33	Lower Hutt City	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F3786201	24/07/2023 10:31:27	Auckland	Structure fire with no damage	Ceiling and floor assembly	Short circuit, earth fault	Not Recorded
F3787544	26/07/2023 10:22:57	Taranua District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3789181	28/07/2023 20:22:18	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Deliberately lit fire - not classified above	Confined to room of origin
F3790049	30/07/2023 14:17:13	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3791595	2/08/2023 5:54:09	Tauranga City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F3792516	3/08/2023 13:09:35	Ruapehu District	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to room of origin
F3792863	4/08/2023 6:49:48	Porirua City	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F3793331	4/08/2023 18:03:36	Far North District	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to room of origin
F3794465	7/08/2023 10:54:25	Hamilton City	Structure fire with no damage	Ceiling and roof assembly	Heat source too close to combustibles	Not Recorded
F3795087	8/08/2023 11:25:14	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Extended beyond structure of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3799738	16/08/2023 7:14:52	South Wairarapa District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to fire cell of origin
F3803181	22/08/2023 9:31:31	Kaikoura District	Structure fire with damage	Ceiling and floor assembly	Rekindled from previous fire, Re-ignition	Confined to object of origin
F3806195	26/08/2023 23:16:42	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to fire cell of origin
F3807125	28/08/2023 19:45:35	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3810081	2/09/2023 0:13:05	Horowhenua District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to object of origin
F3811557	4/09/2023 16:30:34	Upper Hutt City	Structure fire with damage	Ceiling and floor assembly	Undetermined	Confined to structure of origin
F3811702	4/09/2023 20:43:27	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F3814614	9/09/2023 5:47:31	Taupo District	Structure fire with damage	Ceiling and roof assembly	Construction deficiency	Confined to structure of origin
F3815830	11/09/2023 11:13:50	Waitomo District	Structure fire with damage	Ceiling and roof assembly	Equipment overloaded	Confined to part of room or area of origin
F3817461	13/09/2023 16:29:51	Christchurch City	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3824093	22/09/2023 13:43:44	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3824908	23/09/2023 20:45:50	Waipa District	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to object of origin
F3826033	26/09/2023 8:17:53	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to structure of origin
F3828882	30/09/2023 19:19:25	South Wairarapa District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to part of room or area of origin
F3832039	5/10/2023 14:13:16	Auckland	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3832370	6/10/2023 5:19:34	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3834268	9/10/2023 18:50:11	Waitaki District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to object of origin
F3835103	11/10/2023 7:27:27	Manawatu District	Structure fire with damage	Ceiling and floor assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F3838399	16/10/2023 6:01:30	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F3842152	21/10/2023 14:36:36	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3843063	23/10/2023 13:31:17	Wairoa District	Structure fire with damage	Ceiling and roof assembly	High temperature	Confined to structure of origin
F3844457	25/10/2023 17:32:59	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to structure of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3845020	26/10/2023 13:38:27	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to room of origin
F3845368	27/10/2023 6:41:34	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Extended beyond structure of origin
F3848310	31/10/2023 16:15:00	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to floor of origin
F3848453	31/10/2023 19:45:08	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3850102	3/11/2023 9:56:45	Lower Hutt City	Structure fire with no damage	Ceiling and roof assembly	Lack of maintenance	Not Recorded
F3850537	3/11/2023 22:52:29	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to structure of origin
F3850588	4/11/2023 4:12:49	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to fire cell of origin
F3851120	5/11/2023 1:26:15	Far North District	Structure fire with damage	Ceiling and floor assembly	Short circuit, earth fault	Confined to structure of origin
F3851317	5/11/2023 11:01:54	Ashburton District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3855441	11/11/2023 12:30:31	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3856273	13/11/2023 4:00:14	Whakatane District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3864952	26/11/2023 5:45:06	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to fire cell of origin
F3874043	10/12/2023 8:03:55	Auckland	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to part of room or area of origin
F3881145	20/12/2023 12:06:57	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3887957	1/01/2024 0:28:33	Christchurch City	Structure fire with damage	Ceiling and roof assembly	People playing with combustibles	Confined to room of origin
F3888802	2/01/2024 14:30:01	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3891105	7/01/2024 11:59:37	Ruapehu District	Structure fire with damage	Ceiling and roof assembly	Construction deficiency	Confined to object of origin
F3891468	8/01/2024 8:52:51	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Extended beyond structure of origin
F3893912	12/01/2024 9:39:23	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3897959	19/01/2024 1:55:11	Tauranga City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3899135	21/01/2024 0:05:12	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to object of origin
F3901665	24/01/2024 21:58:41	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3901681	24/01/2024 23:08:16	Invercargill City	Structure fire with no damage	Ceiling and roof assembly	Automatic control failure	Not Recorded
F3905133	30/01/2024 18:03:50	New Plymouth District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to floor of origin
F3906299	1/02/2024 10:51:22	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to fire cell of origin
F3913295	12/02/2024 15:20:22	Whanganui District	Structure fire with damage	Ceiling and floor assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3913393	12/02/2024 17:53:32	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3917330	18/02/2024 0:43:24	Auckland	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F3923908	26/02/2024 23:17:04	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3925727	29/02/2024 9:31:06	Wellington City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	No damage of this type
F3925727	29/02/2024 9:31:06	Wellington City	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to structure of origin
F3926298	1/03/2024 3:25:44	Napier City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F3928385	4/03/2024 14:08:23	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Extended beyond structure of origin
F3929330	5/03/2024 20:34:09	Napier City	Structure fire with no damage	Ceiling and floor assembly	Undetermined	Not Recorded
F3931624	8/03/2024 22:22:58	Christchurch City	Structure fire with no damage	Ceiling and roof assembly	Animal	Not Recorded
F3935487	14/03/2024 17:05:37	Central Otago District	Structure fire with damage	Ceiling and floor assembly	Unattended cooking	Extended beyond structure of origin
F3935709	15/03/2024 6:50:30	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3936733	16/03/2024 20:05:51	Christchurch City	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F3936975	17/03/2024 11:11:11	Palmerston North City	Structure fire with damage	Ceiling and floor assembly	Careless disposal or use: cigarettes, ashes, embers	Confined to part of room or area of origin
F3937999	18/03/2024 20:51:42	Hastings District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3938509	19/03/2024 14:20:56	Taupo District	Structure fire with damage	Ceiling and floor assembly	Equipment unattended	Confined to structure of origin
F3942330	25/03/2024 3:48:07	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3942402	25/03/2024 8:28:48	Far North District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3945764	30/03/2024 9:30:46	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin



# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3946133	30/03/2024 23:04:29	New Plymouth District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F3948924	4/04/2024 15:09:02	Dunedin	Structure fire with no damage	Ceiling and roof assembly	Heat source too close to combustibles	Not Recorded
F3950641	7/04/2024 13:12:06	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Construction deficiency	Confined to part of room or area of origin
F3954741	13/04/2024 17:26:37	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to structure of origin
F3954798	13/04/2024 20:02:31	Auckland	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to part of room or area of origin
F3955049	14/04/2024 12:06:59	Auckland	Structure fire with damage	Ceiling and roof assembly	Construction deficiency	Confined to floor of origin
F3955866	15/04/2024 17:48:01	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F3958746	19/04/2024 15:44:31	Kapiti Coast District	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F3960625	22/04/2024 19:44:25	Porirua City	Structure fire with damage	Ceiling and roof assembly	Failure to clean	Confined to part of room or area of origin
F3963347	26/04/2024 22:33:00	Westland District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F3965018	29/04/2024 14:18:29	Auckland	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3966101	30/04/2024 20:04:37	Invercargill City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to room of origin
F3967591	3/05/2024 8:23:38	Waikato District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to part of room or area of origin
F3967744	3/05/2024 10:42:47	Whakatane District	Structure fire with damage	Ceiling and floor assembly	Other electrical failure	Confined to fire cell of origin
F3968146	4/05/2024 3:08:10	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3969017	5/05/2024 14:03:56	Central Hawke's Bay District	Structure fire with damage	Ceiling and roof assembly	Animal	Extended beyond structure of origin
F3969904	7/05/2024 1:09:50	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F3971191	8/05/2024 14:19:23	Masterton District	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to part of room or area of origin
F3974081	13/05/2024 6:54:35	Auckland	Structure fire with damage	Ceiling and roof assembly	Failure to clean	Extended beyond structure of origin
F3974620	13/05/2024 18:35:36	Whangarei District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3976188	15/05/2024 17:53:15	Selwyn District	Structure fire with no damage	Ceiling and roof assembly	Failure to clean	Not Recorded
F3976858	16/05/2024 17:37:24	Opotiki District	Structure fire with damage	Ceiling and floor assembly	Suspicious	Confined to structure of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F3976940	16/05/2024 21:56:15	Grey District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3976982	17/05/2024 0:16:26	Opoitiki District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F3979607	21/05/2024 8:40:23	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F3982794	26/05/2024 7:24:51	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F3984618	29/05/2024 10:40:16	Auckland	Structure fire with no damage	Ceiling and roof assembly	Short circuit, earth fault	Not Recorded
F3986970	1/06/2024 11:25:27	Hastings District	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F3988020	3/06/2024 12:10:22	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F3993003	11/06/2024 18:03:25	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F3995634	15/06/2024 22:03:30	Auckland	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to room of origin
F3996595	17/06/2024 17:21:52	New Plymouth District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F3997962	19/06/2024 19:19:29	Far North District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to part of room or area of origin
F4004079	30/06/2024 9:22:46	Auckland	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F4007354	6/07/2024 11:32:37	Hauraki District	Structure fire with damage	Ceiling and roof assembly	Unknown / Other (capture details in the COMMENTS tab)	No damage of this type
F4008681	9/07/2024 7:25:49	Wellington City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F4009319	9/07/2024 21:38:19	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F4011265	12/07/2024 22:56:38	Wairoa District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to structure of origin
F4011275	12/07/2024 23:41:07	Auckland	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F4012585	15/07/2024 14:45:01	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F4014278	18/07/2024 9:47:49	Thames-Coromandel District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F4015624	20/07/2024 16:51:05	Westland District	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to part of room or area of origin
F4015731	20/07/2024 22:43:59	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to fire cell of origin
F4019975	28/07/2024 10:37:23	Grey District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to fire cell of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F4022979	2/08/2024 16:43:01	Queenstown	Structure fire with damage	Ceiling and roof assembly	Heat source too close to combustibles	Confined to fire cell of origin
F4026639	9/08/2024 1:35:10	Far North District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Extended beyond structure of origin
F4027067	9/08/2024 16:12:23	Auckland	Structure fire with damage	Ceiling and roof assembly	Equipment overloaded	Confined to fire cell of origin
F4027466	10/08/2024 15:17:04	Stratford District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4028463	12/08/2024 18:16:27	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to object of origin
F4030047	14/08/2024 21:33:59	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to room of origin
F4035260	22/08/2024 23:51:01	Auckland	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Confined to part of room or area of origin
F4036403	25/08/2024 5:03:06	Clutha District	Structure fire with damage	Ceiling and floor assembly	Equipment overloaded	Confined to room of origin
F4038115	28/08/2024 0:23:04	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4040605	1/09/2024 2:23:24	Auckland	Structure fire with damage	Ceiling and roof assembly	Lightning	Confined to structure of origin
F4040833	1/09/2024 12:24:52	Auckland	Structure fire with damage	Ceiling and roof assembly	Lightning	Confined to fire cell of origin
F4041090	2/09/2024 1:43:58	Far North District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Extended beyond structure of origin
F4044960	7/09/2024 23:17:07	Auckland	Structure fire with damage	Ceiling and floor assembly	Part failure, leak or break	Confined to part of room or area of origin
F4047446	11/09/2024 20:26:22	Auckland	Structure fire with damage	Ceiling and roof assembly	Suspicious	Confined to structure of origin
F4048779	13/09/2024 17:52:17	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to fire cell of origin
F4049308	14/09/2024 18:40:25	Auckland	Structure fire with damage	Ceiling and floor assembly	Undetermined	Confined to structure of origin
F4052854	20/09/2024 18:08:30	Buller District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to fire cell of origin
F4054135	23/09/2024 11:35:58	Auckland	Structure fire with damage	Ceiling and roof assembly	Carelessness with material ignited - other	Confined to part of room or area of origin
F4055155	24/09/2024 17:28:57	Lower Hutt City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to object of origin
F4055289	25/09/2024 1:57:35	Far North District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4061024	3/10/2024 21:54:49	Selwyn District	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F4062136	5/10/2024 12:31:00	Palmerston North City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F4062363	5/10/2024 21:50:03	Waimakariri District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F4068911	16/10/2024 23:09:47	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F4069013	17/10/2024 7:58:14	Dunedin City	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to part of room or area of origin
F4070309	18/10/2024 21:58:28	South Waikato District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F4083860	8/11/2024 19:39:45	Whakatane District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4088775	15/11/2024 21:04:33	Palmerston North	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F4089664	17/11/2024 19:06:27	Napier City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4092256	21/11/2024 9:05:38	Auckland	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F4096626	27/11/2024 13:09:52	Napier City	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to floor of origin
F4100102	2/12/2024 16:16:37	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4104553	8/12/2024 9:24:26	Taupo District	Structure fire with no damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Not Recorded
F4104794	8/12/2024 17:11:31	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Poor Workmanship	Confined to part of room or area of origin
F4108729	13/12/2024 18:05:46	Auckland	Structure fire with damage	Ceiling and roof assembly	Exposure fire	No damage of this type
F4109409	14/12/2024 22:40:37	Buller District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4109590	15/12/2024 9:42:37	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to structure of origin
F4110745	16/12/2024 22:12:22	Auckland	Structure fire with no damage	Ceiling and roof assembly	Part failure, leak or break	Not Recorded
F4112813	19/12/2024 14:45:05	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4115097	23/12/2024 13:33:20	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to part of room or area of origin
F4116629	25/12/2024 12:08:33	Tararua District	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to room of origin
F4117211	26/12/2024 19:29:12	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to floor of origin
F4118441	29/12/2024 6:33:46	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4118571	29/12/2024 11:29:11	Ashburton District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin

# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F4119256	30/12/2024 19:35:46	Tasman District	Structure fire with damage	Ceiling and roof assembly	Lightning	Confined to object of origin
F4121385	3/01/2025 21:58:23	Buller District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to part of room or area of origin
F4121453	4/01/2025 5:18:49	Buller District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to fire cell of origin
F4121556	4/01/2025 11:37:42	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	No damage of this type
F4122503	6/01/2025 13:16:50	Napier City	Structure fire with damage	Ceiling and roof assembly	Failure to clean	Extended beyond structure of origin
F4124290	9/01/2025 15:21:48	Whangarei District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F4127984	15/01/2025 4:50:04	Auckland	Structure fire with damage	Ceiling and roof assembly	Installation deficiency	Extended beyond structure of origin
F4129776	17/01/2025 13:37:57	Auckland	Structure fire with damage	Ceiling and roof assembly	Short circuit, earth fault	Confined to part of room or area of origin
F4132288	21/01/2025 15:55:33	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	No damage of this type
F4134548	24/01/2025 18:55:03	Carterton District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4136162	27/01/2025 15:14:41	Auckland	Structure fire with damage	Ceiling and roof assembly	Lack of maintenance	Confined to part of room or area of origin
F4136293	27/01/2025 18:56:18	Hastings District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F4140049	2/02/2025 3:10:17	Whakatane District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F4144597	8/02/2025 13:11:34	Opotiki District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to structure of origin
F4155449	23/02/2025 17:30:57	Rotorua District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to floor of origin
F4155957	24/02/2025 12:07:25	Waitomo District	Structure fire with no damage	Ceiling and roof assembly	Undetermined	Not Recorded
F4156948	25/02/2025 13:40:39	Tasman District	Structure fire with damage	Ceiling and roof assembly	Equipment not being operated properly	Confined to structure of origin
F4164193	6/03/2025 14:41:33	Otorohanga District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to fire cell of origin
F4165281	8/03/2025 4:45:11	Tararua District	Structure fire with no damage	Ceiling and roof assembly	Unlawful	Not Recorded
F4165939	9/03/2025 10:37:41	Auckland	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to part of room or area of origin
F4166233	10/03/2025 4:24:13	Taupo District	Structure fire with damage	Ceiling and roof assembly	Unattended cooking	Confined to room of origin
F4168313	12/03/2025 11:35:37	Waimakariri District	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to structure of origin



# OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F4168835	13/03/2025 3:02:29	Hurunui District	Structure fire with damage	Ceiling and floor assembly	Operating deficiency - not classified above	Confined to part of room or area of origin
F4173233	19/03/2025 4:19:45	Gisborne District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to structure of origin
F4177047	24/03/2025 12:08:32	Auckland	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4177263	24/03/2025 16:04:10	Auckland	Structure fire with damage	Ceiling and roof assembly	Combustible placed too close to heat source	Confined to part of room or area of origin
F4178929	26/03/2025 17:22:32	Waipa District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to structure of origin
F4184500	3/04/2025 15:17:28	Nelson City	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F4184758	4/04/2025 3:16:31	Auckland	Structure fire with damage	Ceiling and roof assembly	Equipment overloaded	Confined to structure of origin
F4185104	4/04/2025 12:12:06	Timaru District	Structure fire with no damage	Ceiling and roof assembly	Unable to classify	Not Recorded
F4186180	6/04/2025 0:43:55	Ashburton District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F4187073	7/04/2025 12:54:05	Waitaki District	Structure fire with no damage	Ceiling and roof assembly	Short circuit, earth fault	Not Recorded
F4189662	10/04/2025 19:39:47	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to part of room or area of origin
F4190489	12/04/2025 0:30:32	Waipa District	Structure fire with damage	Ceiling and roof assembly	Carelessness with heat source - Other	Confined to part of room or area of origin
F4192573	15/04/2025 7:42:33	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to structure of origin
F4193159	15/04/2025 17:17:36	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Pyrophoric	Confined to part of room or area of origin
F4196014	19/04/2025 1:13:22	Auckland	Structure fire with damage	Ceiling and roof assembly	Lightning	Confined to part of room or area of origin
F4197485	21/04/2025 16:02:52	Paraparaumu	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to structure of origin
F4199899	25/04/2025 11:22:41	Timaru District	Structure fire with no damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Not Recorded
F4201237	27/04/2025 20:37:40	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to fire cell of origin
F4202816	29/04/2025 20:57:54	Timaru District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F4203733	1/05/2025 3:28:15	Marlborough District	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F4205307	2/05/2025 16:16:20	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Animal	Confined to part of room or area of origin
F4215246	16/05/2025 22:15:46	Selwyn District	Structure fire with damage	Ceiling and floor assembly	Careless disposal or use: cigarettes, ashes, embers	Confined to floor of origin

## OIA 2025-00018955 Residential structure fires by location of origin

Between 06 Aug 2020 and 06 Aug 2025

Where LOC = 184 - Ceiling and roof assembly & 183 - Ceiling and floor assembly

CAD#	Date/Time	TLA	Incident Type Name	Location of Origin Name	Fire Cause Name	Flame Damage Name
F4216153	18/05/2025 16:31:06	Timaru District	Structure fire with damage	Ceiling and roof assembly	Part failure, leak or break	Confined to floor of origin
F4216992	19/05/2025 19:42:12	Matamata-Piako District	Structure fire with damage	Ceiling and roof assembly	Unknown / Other (capture details in the COMMENTS tab)	Confined to room of origin
F4220465	24/05/2025 21:37:46	Buller District	Structure fire with damage	Ceiling and roof assembly	Operating deficiency - not classified above	Confined to room of origin
F4220626	25/05/2025 8:30:56	Tasman District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Confined to room of origin
F4224665	30/05/2025 19:15:30	New Plymouth District	Structure fire with damage	Ceiling and floor assembly	Operating deficiency - not classified above	Confined to structure of origin
F4225413	1/06/2025 6:24:22	Selwyn District	Structure fire with damage	Ceiling and roof assembly	Other electrical failure	Extended beyond structure of origin
F4228611	6/06/2025 9:27:18	Thames-Coromandel District	Structure fire with damage	Ceiling and roof assembly	Unable to classify	Confined to object of origin
F4229953	9/06/2025 2:28:22	Dargaville	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Extended beyond structure of origin
F4237916	21/06/2025 14:01:08	Thames-Coromandel District	Structure fire with damage	Ceiling and floor assembly	Failure to use ordinary care	Confined to part of room or area of origin
F4238033	21/06/2025 18:30:57	Central Otago District	Structure fire with damage	Ceiling and roof assembly	Unknown / Other (capture details in the COMMENTS tab)	Confined to structure of origin
F4239231	23/06/2025 20:40:16	Western Bay of Plenty District	Structure fire with damage	Ceiling and roof assembly	Undetermined	Confined to object of origin
F4242476	28/06/2025 7:42:00	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Friction (sparks etc.)	Confined to part of room or area of origin
F4245929	4/07/2025 5:44:06	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Exposure fire	Confined to fire cell of origin
F4248111	8/07/2025 5:25:21	Hamilton City	Structure fire with damage	Ceiling and roof assembly	Rekindled from previous fire, Re-ignition	Confined to structure of origin
F4248718	9/07/2025 0:46:40	Manawatu District	Structure fire with no damage	Ceiling and roof assembly	Other electrical failure	Not Recorded
F4248869	9/07/2025 10:06:13	Auckland	Structure fire with damage	Ceiling and roof assembly	Equipment overloaded	Confined to part of room or area of origin
F4249165	9/07/2025 16:51:17	Auckland	Structure fire with damage	Ceiling and roof assembly	Combustible placed too close to heat source	Confined to part of room or area of origin
F4255733	20/07/2025 13:51:17	Palmerston North City	Structure fire with no damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Not Recorded
F4257264	23/07/2025 6:33:04	Wellington City	Structure fire with damage	Ceiling and roof assembly	Design, construction or installation fault - Other	Confined to part of room or area of origin
F4262644	30/07/2025 19:08:05	Christchurch City	Structure fire with damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Confined to part of room or area of origin
F4264070	2/08/2025 4:32:48	Waikato District	Structure fire with no damage	Ceiling and roof assembly	Mechanical failure, malfunction - Other	Not Recorded