

Fire Related Product Recall Notice

Date issued: 30 June 2017



Horizon Hobby Remote-Controlled Model Vehicles

Horizon Hobby LLC are recalling various models of Remote –Controlled vehicles.

Problem

The vehicle's electronic speed control (ESC) can fail and short circuit, posing a fire hazard.



Details

Electronic speed control, ESC #DYNS2201 supplied with:
ECX Ruckus, and Torment remote-controlled model vehicles.

ECX03130T1 - ECX03130T2 - ECX03131T1 - ECX03131T2
ECX03133T1 - ECX03133T2 - ECX03154

What to do

Stop using the affected products and contact your dealer or hot-RC for instructions on receiving a free replacement ESC.

Contact

Contact New Zealand supplier

<http://www.hotrc.co.nz/index.php?route=information/contact>

<http://www.horizonhobby.com/>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever